


The End Wrench®

A Publication for Professional Repair Technicians from Subaru N.E.W. Horizons Dealers www.endwrench.com

Subaru Engine Performance Update

SEMA Show Issue
See Us At LVCC North Hall, Booth 11044



Information Inside



CAUTION!

This ad contains fast moving parts.

More new performance parts for the Subaru Impreza WRX, WRX STi and 2.5RS models!

To meet the Subaru enthusiast's relentless demand for even greater performance and—let's be honest—even hotter appearance, Subaru continues to expand our line of Subaru Performance Tuning (SPT) parts including STI, Eibach® and KYB® products. STI ceramic/metallic clutch discs and clutch covers. STI chromium/molybdenum flywheels. Heavy duty STI timing belts and brake hose sets. STI performance suspension kits. Titanium shift knobs, turbo gauges and more. They're all available now at your local authorized Subaru dealer, or check out the full line of Genuine Subaru Performance Parts at www.spt.subaru.com.

17" BBS Multi-Spoke Forged
Aluminum Wheel

Turbo Gauge



STI 5mm Clutch
Disc and Cover

Performance
Exhaust System

Performance Strut Set

STI Short-Throw Shifter

Note: Not all parts applicable to all models/model years.

SUBARU 
DRIVEN BY WHAT'S INSIDE™

The End Wrench® and www.endwrench.com are quarterly publications of Subaru of America, Inc.

No part of this newsletter may be reproduced without the express written permission of Subaru of America, Inc.

Subaru Consultants:

**Bruce Barker
Norm Hunsinger
Joseph Kuter**

Editorial and Circulation Offices:
598 Pine Point Drive
Akron, Ohio 44333
Phone: 330.666.9886

Caution:
Vehicle servicing performed by untrained persons could result in serious injury to those persons or others.

Information contained in this publication is intended for use by trained, professional auto repair technicians ONLY. This information is provided to inform these technicians of conditions which may occur in some vehicles or to provide information which could assist them in proper servicing of these vehicles.

Properly trained technicians have the equipment, tools, safety instructions, and know-how to perform repairs correctly and safely. If a condition is described, DO NOT assume that a topic covered in these pages automatically applies to your vehicle or that your vehicle has that condition.

BRAT, Forester, Impreza, Justy, Legacy, Loyale, Outback, Subaru SVX and WRX are Subaru Registered Trademarks.

The End Wrench
www.endwrench.com

A Publication for Professional Repair Technicians from Subaru N.E.W. Horizons Dealers

inside

4 H-4 and H-6 Engine Service



The engines used in all Subaru models have received major changes and upgrades in the past few years, and some completely new engines have also been introduced. We'll explain the changes, especially as they relate to your vehicle service efforts.

6 O.E. PRO Corner



Our commitment to help you keep your customers satisfied and coming back to you for their Subaru service and repairs has not changed. In fact, there are more parts being offered under the Subaru O.E. PRO banner than ever.

16 WRX Turbo Tech



The 2.0 liter WRX engine is the first turbocharged Subaru engine since the 1994 Legacy 2.2 liter. This article explains the technology found in this new engine, as well as several important service procedures and cautions.

24 Insider Info




An assortment of Subaru service bulletins and time-saving tips for aftermarket technicians, this time with a late model engine service slant.

26 Subaru N.E.W. Horizons Dealer Listings




Subaru N.E.W. Horizons Dealers have been recognized for their outstanding performance in serving the wholesale market. They provide you with a direct wholesale parts hotline and also maintain a large inventory of competitively priced Genuine Subaru Parts.

Subaru Internet Resources



Additional parts and service information is available online. *The End Wrench* can also be found at www.endwrench.com. Log onto <http://techinfo.subaru.com> for access to Subaru service manuals, service bulletins, Tech Tips, newsletters and owner's manuals. You can also select from a range of SPT Performance Parts at www.spt.subaru.com.



H-4 and H-6 Engine Service

The engines used in all Subaru models have received major changes and upgrades in the past few years, and some completely new engines have also been introduced. We'll explain the changes, especially as they relate to your vehicle service efforts.

2.2 Liter Phase 1 Engine Enhancements

The 2.2 liter Phase 1 engine has been enhanced, starting with 1997 model year. The single overhead camshaft (SOHC) engines have had internal and external changes that yield an approximately 10% increase in power and 3% increase in fuel economy. Accomplishing this involves many factors, one of which is engine friction reduction.

The piston, a major source of engine friction, has been coated with a friction reducing agent called molybdenum. This thin coating not only allows a smoother travel through the cylinder but also reduces cylinder wall scuffing. This coating will wear off over time and is not an indication of a problem.

The skirt of the piston has been reshaped and the overall weight has

been reduced by approximately 100 grams. Compression ratio has been increased to 9.7 to 1 by reshaping the crown of the piston. This eliminates the clearance that was available between the piston at TDC and a fully opened valve. Piston pin offset has been changed to 0.5 mm. Piston to cylinder wall clearance has been reduced by increasing the piston diameter.

Another source of engine friction is the valvetrain. Hydraulic lash adjusters are always in contact with the camshaft or valve rockers. The hydraulic pressure of the lash adjuster must be overcome during operation and engine starting. To overcome this situation and to contribute to the total reduction of friction loss, the SOHC engines have solid valve adjusters.

The scheduled service of these valvetrains is set at 100,000 miles. The SOHC engine uses an adjustment screw and locknut. Follow the instructions below for setup and adjustment. Tools required for 2.2 valve adjustment are: thickness gauge, 10mm wrench, stubby standard screwdriver, crankshaft wrench.

Step 1

Remove the right bank camshaft outer cover. Standard valve clearance:

Intake valves 0.20 ± 0.02 mm

Exhaust valves 0.25 ± 0.02 mm.

Rotate the engine until the arrow on the camshaft sprocket is at 12:00. The camshaft sprocket has an arrow and a mark for belt timing. Make certain the arrow is used, not the mark for valve adjustment only.

Using a standard thickness gauge, measure the clearance of the intake and exhaust valves on cylinder 1 only. Adjust the clearance by loosening the locknut and turning the adjustment screw until the proper clearance is obtained.



Adjusting Valve Clearance

Step 2

Rotate the engine until the arrow on the camshaft sprocket is at 3:00. Check and adjust the clearance of the intake and exhaust valves on cylinder 3 only.

Step 3

Rotate the engine until the arrow on the camshaft sprocket is at 6:00. Check and adjust the clearance of the intake and exhaust valves on cylinder 2 only.

Other Engine Modifications

The intake manifold has been reshaped to increase the airflow mass and speed, contributing to improved low and mid engine speed operation. Components located on the intake manifold have been relocated as compared to the 1996 models. EGR Solenoid, Purge Control Solenoid, etc.

1999 2.2 Liter Phase 2 Engine Enhancements

All 2.2 liter engine for 1999 are the Phase 2 design. The 2.2 liter Phase 2 engines are a SOHC design, with a newly-designed cylinder head. Changes in the 2.2 liter Phase 2 engines are as follows:

- The engine and transmission are fastened with six bolts and two studs.
- The thrust bearing has been moved to the number 5 position.
- The oil groove in the number 1 and 3 have been changed to supply additional lubrication to the crank journal.

Additional Phase 2 Engine Features

- The cylinder head is a two-rocker shaft, solid type valve system with roller followers.
- The valves are positioned at a larger angle than previous model years. The intake valves are positioned 23 degrees off-center with the exhaust valves positioned 20 degrees off-center. Prior model year engines utilized a 15-degree positioning angle.



Identification of Rocker Arms

- The intake rocker arms are marked so they are correctly placed on the rocker shaft when servicing. An IN1 or IN2 will be embossed on each rocker arm. As viewed from the front of the engine the Number 1 intake valve of each cylinder and the number 2 intake valve have an IN1 marked and IN2 marked rocker arm that mates with it. New IN1 rocker arms can also be identified by a Green painted mark on the top of the rocker arm. The IN2 rocker arms have a white mark. Proper positioning is maintained through the use of a wave washer located between the rocker shaft arm and rocker arm shaft support.
- The camshaft is secured to the cylinder head with the camcase. An oil passage in the cylinder head provides the passageway in the camcase with oil that leads to the intake rocker shaft. Oil from the camshaft is collected on the opposite side of the passageway leading to the intake rocker shaft to provide oil to the exhaust rocker shaft.
- Sealing of the camcase is accomplished by using a thin layer of Three Bond (1280B) applied in the channel around the camcase edge. After the three bond is applied, the camcase must be installed to

Continued on page 8.



Original Equipment Parts/
Professional Service

Subaru Takes Care of Business On the Road. At the Track. In the Field.

There's great satisfaction when someone you depend on comes through for you. That kind of trust and teamwork isn't easily earned. At Subaru, we appreciate the support from independent repair technicians throughout the country. You play an important role in keeping Subaru owners happy with their car's performance by using Genuine Subaru Parts on a regular basis. In fact, more Genuine Subaru Parts are being purchased by independents like you than ever before.

So, it's only right that you feel that you can depend on Subaru and the O.E.PRO team when it comes to helping you do your job. That's why we go to great lengths to ensure our prices are competitive. So you have margins that give you breathing room. It's also why we test every Genuine Subaru Part to guarantee it performs up to original equipment specifications.

To help your business, we also continually add new parts to the O.E.PRO Program and to the SPT and STI Performance Parts lineup. We back that up with our popular performance parts Web site, www.spt.subaru.com. Keeping a display in your shop and promoting your performance and styling capabilities can help generate a whole new cash flow.

Another way that Subaru also helps independents thrive is with a substantial investment in the racing scene from the international road rallies to the local SCCA events. Beside the fact that we love driving and watching Subaru vehicles perform at these venues, it helps spread the word that Subaru is a serious performance machine that can more than hold its own. And that's what you want in a partner: someone who takes care of business in every way that matters.

Subaru Spotlights SPT and Performance at SEMA

With the introduction of many new SPT and STI Performance Parts, including the great new 3-inch "cat-back" WRX Performance Exhaust System pictured here, Subaru should be drawing quite a crowd at the Specialty Equipment Marketing Association show taking place November 4 – 7 at the Las Vegas Convention Center. This year's booth for

Subaru (#11044 - North Hall) will be a real treat. It'll showcase a variety of hot Subaru project vehicles, the Easy Street Motorsports Drag Racing 740 horsepower WRX, a 500 horsepower Baja, a replica of the

Subaru U.S. Rally Team car and more. From new performance suspension bushings that help improve handling to new STI transmission and engine mounts to stylish SPT accessories like the Momo shift knob, plenty of interest at SEMA will be focused on the incredible Subaru Performance Tuning story.



This 3-inch "cat-back" muffler system is just one of the many new Subaru Performance Parts that will generate a lot of interest from your performance-oriented customers.

The Thrill of High Performance Racing

Over the past few years, Subaru has earned great respect in racing circles. As an independent Subaru automotive technician, you have a great opportunity to cash in on the huge interest in racing and performance with sales and installation of both SPT and STI Performance Parts and accessories. You can turn a Legacy, RS or WRX into a performance machine. Here's a quick review of where to find the thrills and opportunities in the exciting world of automotive racing.

Rally Racing Offers True Excitement and Speed

The draw of rally racing is the thrill of following a course through challenging terrain at the fastest time possible. When the Subaru Rally team takes on SCCA courses in the ProRally circuit, they know they can depend on the response of their carefully prepped WRX vehicles to handle everything from the wintry roads of "SnoDrift" in Michigan to the dusty switchbacks of "Rim of the World" in California. And their performance on the international rally scene has also been impressive. You can get your own customers involved in local rallies that the SCCA runs and share in the excitement by helping them create a car that's a kick to drive.



Drag Racing WRX Sets a Blistering Pace

Ever since two cars lined up side-by-side, drag racing has been part of the American landscape. Subaru has been making a big name for itself lately in this category, too, with a revved-up WRX that blisters down the quarter mile drag strip in 9.75 seconds at more than 141 mph. Featured on the Easy Street Motorsports Web site and in its own racing tour, this Subaru can inspire drag racing fans in your area to tune-up their own vehicles with performance exhaust systems, the high flow air intake, short throw shifter and more.

Solo Racing Lets Drivers Push their Skills to the Limit

Solo racing pits drivers against a course that tests responsiveness, speed and agility. There's a huge sub-culture of enthusiasts from the ProSolo driver to the local speed demon out there racing around the track and pylons while putting his or her driving skills and Subaru to the test. The SCCA regularly hosts solo events and you can help these performance thrill-seekers get the most out of their car with the performance parts you offer.

Performance Web Sites Worth A Look

There are plenty of Web sites you can visit to learn more about the variety of racing events held all around the country. Naturally, you should check out Subaru's own site at www.rally.subaru.com. It features pictures of the cars and drivers, descriptions of the events and more. The Sports Car Club of America's site, www.scca.org, describes all forms of rally, solo and club racing venues you can share with your customers. International rallies are covered in www.rally-europe.co.uk and American rallies are described at www.goss.com/rally.htm. To learn more about the drag racing WRX, visit www.esxmotorsports.com. Naturally, the site to find the finest in Subaru Performance Parts and the dealers who you can buy them from is www.spt.subaru.com.

H-4 and H-6 Engine Service

the cylinder head and onto the engine before the three bond has time to cure. Failure to do this will result in oil leaks.

Note: Cylinder head and camcase must be replaced together (line bored).

- The sparkplug pipe is pressed into the cylinder head and is not serviceable. If it becomes damaged the cylinder head must be replaced. The seals installed onto the ends of the sparkplug pipes seal against the valve covers and should be replaced when the valve cover is removed.
- Timing belt marks for the left bank are on the inner timing belt cover and the edge of the camshaft sprocket. The crankshaft timing mark remains on the reluctor with engine block mark, just below the crank angle sensor. The right bank camshaft sprocket has a mark at the edge that is matched with the seam line formed by the meeting of the camcase and cylinder head (12:00 position).
- The right bank timing mark can be checked with outer cover in place using the provided window.
- Pistons on the 2.2 liter engines have a 0.5 mm offset with the engine having a compression ratio of 10.0 to 1. The horsepower has increased to 142 hp @ 5600 RPM. Maximum torque is 149 ft. lbs @ 3600 RPM.
- The 2.5 liter engine uses double overhead camshafts that are belt-driven. Belt tension is maintained through the use of the hydraulic tensioner which is also used on the 2.2 and 3.3 liter engine.
- Camshaft sprockets are constructed of a resin type material with a metal key pressed into the sprocket for maintaining proper sprocket to shaft orientation.

The timing marks on the left bank intake camshaft sprocket are positioned at 12 o'clock and 6 o'clock. The 12 o'clock mark, which aligns with a timing mark on the timing belt housing, is used for camshaft to engine timing. The 6 o'clock mark is used for timing the intake camshaft to the exhaust camshaft, which has a timing mark at the 12 o'clock positions. The remaining timing mark on the exhaust camshaft

sprocket, positioned at the 3 o'clock, ensures the exhaust camshaft sprocket is timed correctly to the engine. With all timing marks aligned, the intake and exhaust camshaft are in a loaded state. If the timing belt were removed, the camshafts would suddenly revolve from the force of the valve springs. To prevent this from occurring maintain the intake camshaft position and carefully unload the camshaft by allowing it to slowly rotate counterclockwise, (exhaust clockwise) while removing the belt.

Note: Use special tool J-42908 for holding camshaft sprockets during belt installation. It may also be used for loading as well as unloading the camshafts. Caution: valve damage will occur if both camshafts are turned incorrectly after the timing belt has been removed.



Camshaft Sprocket Timing Marks (Right Bank)

- The right bank intake sprockets timing marks are similar in location and purpose to the left bank. However, the exhaust camshaft sprocket on the right bank uses a timing mark at the 9:00 o'clock position to ensure proper camshaft to engine timing.
- To access the cylinder head bolts, the camshafts must be removed. Follow the procedure outlined in the Subaru service manual for performing this task. The camshafts are held to the cylinder head with bearing caps that are marked (right side) I1TD, I3TD, E1TD, E3TD.
- 2.5 liter engine head gaskets are identified by the three notches located along the gaskets edge, 2.2 liter normally aspirated engine head gaskets have only two notches.



Original Equipment Parts/
Professional Service


Genuine SUBARU REMANUFACTURED PARTS



...meet original equipment specifications, perform like new and save money.

Want to save money on big-ticket auto parts without risking a thing? Consider using Genuine Subaru Remanufactured Parts. All of them meet the strictest OEM specifications and fit and function like new Genuine Subaru parts.

They cost less because they cost less to build. Built using only the best cores that are disassembled, cleaned, machined and refitted to strict quality standards, each Genuine Subaru Remanufactured Part is designed to offer trouble-free driving and unsurpassed reliability. Of course, they're all backed by the Genuine Subaru Parts Limited Warranty. So call your local authorized Subaru dealer for prices and details or visit www.endwrench.com today.



Genuine Subaru Remanufactured Parts

Brake Calipers	Includes front and rear calipers
Electrical	Includes alternators, starters and digital dashes
Automatic Transmissions	Includes AWD and FWD
Drive Train	Includes rear differentials and front axles

Caution: The bolt patterns for both gaskets are the same but are not interchangeable.

- The cylinder head bolts for the 2.5 liter engine are much shorter than those of the 2.2 liter engine, and are not interchangeable.
- Valve servicing is accomplished by utilizing special tool 499718000 and a universal valve spring compressor. The single valve spring is color coded red and rests on a metal spring seat which is used to prevent cylinder head wear. A special tool (498267700) is required to adjust valve guide height, if replacement is necessary. A valve guide reamer (499767400) and a valve guide remover (499767200) will also have to be used. The hydraulic lash adjuster is of the same type as the 3.3 liter engine and requires no servicing.

- Spark plugs for the 2.5 liter engine are platinum tipped, NGK PFR5B-11. (Same maintenance schedule as the SVX.) 2.2 liter engines use Champion RC10YC4.
- Engine oil viscosity for all '96 Legacy and Outback vehicles is 5W-30 to improve fuel economy.


2.5 Liter Engine Spark Plug Replacement Procedure

1. Remove battery, washer tank and air cleaner.
2. Remove high tension cords.
3. Cover ATF pipes and ABS pipes with cloth to prevent them from damage during replacement of spark plugs.
4. Remove spark plugs by using a general service tool with the special instruction described below.

Installation

1. Set the spark plug into the socket.

2. Tighten the spark plug in the cylinder head with the socket. It is necessary to support the end of the socket by a finger.
3. When the spark plug can be felt to be tightened with 2 or 3 rotations, remove the socket from the spark plug.



Spark Plug Removal

4. Confirm if the spark plug is screwed into the hole properly by touching it with a finger. If it is difficult to touch it by finger, confirm its condition by using mirror.

H-4 and H-6 Engine Service

5. Reset the socket on the plug then tighten it with the proper torque.
6. Install high tension cords.
7. Install battery, washer tank, and air cleaner.

Note: Length L1 (100mm, 3.94") is most important for ease of removal and installation. Wrap points A & B with tape to prevent them from separating during work. An approximate 250mm extension bar is recommended between the ratchet and the universal joint.

1997 Phase 1 2.5 Liter DOHC Engine

The double overhead camshaft engines have had internal and external changes that yield an approximately 10% increase in power and 3% increase in fuel economy. Compression ratio has been increased to 9.7 to 1 by reshaping the crown of the piston. This eliminates the clearance that was available between the piston at TDC and a fully opened valve. Piston pin offset has been changed to 0.5 mm. Piston to cylinder wall clearance has been reduced by increasing the piston diameter.

Another source of engine friction is the valvetrain. Hydraulic lash adjusters are always in contact with the camshaft or valve rockers. The hydraulic pressure of the lash adjuster must be overcome during operation and the most critical time of engine start. To contribute to friction reduction, all DOHC engines have solid valve adjusters.

The scheduled service of these valvetrains is set at 100,000 miles. The DOHC engine uses an adjustment shim. There are 94 shim sizes.


Note: Use a thin nonmagnetic tool placed in the notch of the lash adjuster to remove shim (special tool J-43979).

Note: The printed size of the shim should be installed away from the camshaft lobe.

The space between the valvetrain and the frame rail of a DOHC is somewhat limited, however valve adjustment is possible by performing the following:

Step 1

- Set the crankshaft sprocket at 0 degrees. (use crankshaft wrench)
- Set the left intake camshaft sprocket arrow at 12 o'clock. The camshaft sprocket has an arrow and a mark used for belt timing. Make certain to use the arrow and not the mark for valve clearance check.
- The engine is now set to check the clearance of the exhaust valves on cylinders 1 and 3 only. (Please remember that the profile of a camshaft with solid lifters has a ramp that is used to gradually take up the clearance between the lift of the lobe and the lash adjuster.)
- Measure and record the clearance.



Cams Set for 1 and 3 Exhaust Clearance Measurement

Step 2

- Rotate the crankshaft 180 degrees.
- The left intake camshaft arrow should now be at 3 o'clock.
- Check the clearance of the intake valves on cylinders 1 and 3 only.
- Record the measurement.

Step 3

- Rotate the crankshaft 180 degrees.
- The left intake camshaft arrow should now be at 6 o'clock.
- Check the clearance of the exhaust valves on cylinders 2 and 4 only.
- Record the measurement.

Step 4

- Rotate the crankshaft 180 degrees.
- The left intake camshaft sprocket arrow should now be at 9:00.
- Check the clearance of the intake valves on cylinders 2 and 4 only.
- Record the measurement.

Step 5

- Use the formula below to choose the new shim:



Original Equipment Parts/
Professional Service

Genuine SUBARU MAINTENANCE PARTS



Built to provide peak performance at competitive prices

With dirt, dust, heat, friction and contaminants working to rob vehicles of power, why try to save a few pennies on non-genuine parts that can cost car owners so much more over time? Off-brand parts can result in poor performance, faster wear and possible damage due to poor fit or not being up to specification. But regular maintenance using competitively priced Genuine Subaru Maintenance Parts can help keep your customers' cars running smoothly for years without sacrificing quality or risking trouble.

These high quality parts are engineered to precise specifications so they fit right, perform better and last longer. Take the materials in Genuine Subaru brake pads. They're specially formulated to be compatible with the rotor surface to help

prevent brake chatter, noise and excessive heat build-up, which can impair stopping effectiveness.

For part applications and prices, visit www.endwrench.com and contact your authorized Subaru dealer.



Genuine Subaru Maintenance Parts

Filters	Includes oil, air and fuel filters
Spark Plugs	Includes standard and platinum tip plugs
Brake Pads and Shoes	Includes front and rear plus repair kits
Belts	Includes timing, alternator and a/c belts

Intake valve $S = V + T - .20$
 Exhaust valve $S = V + T - .25$
 S = Shim thickness to be used
 V = Measured valve clearance
 T = Shim thickness in use
 Standard valve clearance
 (Intake valves 0.20 ± 0.02 mm)
 (Exhaust valves 0.25 ± 0.02 mm)

Example:

To solve for the new shim or T :

- Cylinder 1 intake measured valve or clearance is 0.22 mm - no adjustment needed.
- Cylinder 1 exhaust measured valve or clearance is 0.15 mm - adjustment needed.
- Cylinder 3 intake measured valve or clearance is 0.31 mm - adjustment needed.

The shim in use on cylinder 1 exhaust is marked 240. This refers to the shim having a thickness of 2.40 mm.

$T = 2.40$ $S = V + T$ (0.25 mm)
 $V = 0.19$ $S = .19 + 2.4 - (0.25\text{mm})$
 $SVC = 0.25 \pm 0.03$ $S = 2.59 - 0.25\text{mm}$
 (Standard valve clearance) $S = 2.34$

The shim in use on cylinder 3 intake is marked 245. This refers to the shim having a thickness of 2.45 mm.

$T = 2.45$ $S = V + T$ (0.20mm)
 $V = 0.31$ $S = .31 + 2.45 - (.20\text{mm})$
 $SVC = 0.20 \pm 0.03$ $S = 2.76 - .20\text{mm}$
 (Standard valve clearance) $S = 2.56$

Step 6

- The current method of shim replacement is accomplished by removing the camshafts.

Caution: Follow the directions provided in the appropriate serv-

ice manual for camshaft removal and belt installation.

Note: Special tool 498187100 may also be used for this procedure.

1999 2.5 Liter Engine Enhancements: DOHC (Phase 1) and SOHC (Phase 2)

The engines for the 1999 Subaru line are designated Phase 1 and Phase 2. 2.5 liter Legacy engines are the Phase 1 design, while the Impreza and Forester utilize Phase 2 design 2.5 liter engines. The 2.5 liter Phase 2 engines are SOHC engine with a newly designed cylinder head. The (Phase 1) 2.5 liter engine uses the same cylinder head configuration that it has used on prior year models with the crankcase and bell housing sharing the same characteristics of the new Phase 2 engines.

H-4 and H-6 Engine Service

2.5 Liter (Phase 2) SOHC Engine Features

- The cylinder heads have a two-rocker shaft roller solid-type valve system.
- The valves are positioned at a larger angle than previous model years. The intake valves are positioned 23 degrees off center, with the exhaust valves positioned 20 degrees off center. Prior model year engines utilized a 15-degree positioning angle.
- Head gasket thickness is 0.7 mm.
- The intake rocker arms are marked for correct installation on the rocker shaft. An IN1 or IN2 is embossed on each rocker arm. As viewed from the front of the engine, the number 1 intake valve of each cylinder and the number 2 intake valve have an IN1 marked and IN2 marked rocker arm that mates with it. New IN1 rocker arms can also be identified by a green painted mark on the top of the rocker arm. The IN2 rocker arms have a white mark. Proper positioning is maintained through the use of a wave washer located between the rocker shaft arm and rocker arm shaft support.
- The camshaft is secured to the cylinder head with the camcase. An oil passage in the cylinder head provides the passageway in the camcase with oil that leads to the intake rocker shaft. Oil from the camshaft is collected on the opposite side of the passageway leading to the intake rocker shaft to provide oil to the exhaust rocker shaft.
- Sealing of the camcase is accomplished by using a thin layer of Three Bond applied in the channel around the camcase edge. After the three bond (1280B) is applied, the camcase must be installed to the cylinder head and onto the engine before the three bond has time to cure. Failure to do this will result in oil leaks.

Note: The cylinder head and camcase must be replaced together (line bored).

- Timing belt marks on the left bank are on the inner timing belt cover and the edge of the camshaft sprocket. The crankshaft timing mark remains on the reluctor, with the engine block mark just below the crank angle sensor. The right bank camshaft sprocket has a

mark at the edge that is matched with the seam line formed by the meeting of the camcase and cylinder head (12:00 position).

- The right bank timing mark can be checked with outer cover in place, using the provided window.
- Piston design on the 2.5 liter engine remains the same as the 2.2 liter. The compression ratio is 9.7 to 1.

3.0 Liter Engine Features

The EZ-3.0 is the model name (engine designation) for the new six-cylinder engine introduced for the 2001 model year Legacy. The design idea for this engine was to create a power plant that could utilize the current body style, provide more power and decreased exhaust emissions. Many of the features refined for the current four-cylinder engine are employed on the EZ-3.0. However, new features such as Variable Intake Control and timing chain driven camshafts give the new engine a look and operation all of its own.



3.0 Liter Engine Timing Cover

The front of the engine features a large front timing chain cover, secured to the inner cover with 59 bolts. There are four different lengths used and is sealed to the inner cover with Three Bond (1280B). Special care must be used when servicing the timing chain covers to ensure the proper length bolt and sealing procedures are used. A single serpentine belt provides the power to turn all engine accessories. Tension to the belt is controlled with an automatic tensioner. Replace the serpentine belt when the indicator is at or beyond this line.

Additional 3.0 liter engine features:

- Two radiator hose connections are



Genuine SUBARU ENGINE COMPONENTS



...offer exceptional fit, reliability and value.

Don't take chances with your reputation or your customers' satisfaction with rebuilt or inferior aftermarket parts. Genuine Subaru Engine Components are manufactured to demanding original equipment specifications, they're competitively priced and they install easily. No force-fits! More value.

Your local authorized Subaru dealer has a ready supply of a wide variety of applications so you get fast turnaround on everything you order. Of course, every part is backed by the Genuine Subaru Parts Limited Warranty so you know you can trust them to perform flawlessly. Call for details and prices or visit www.endwrench.com.



Genuine Subaru Engine Components

Head Assemblies	Fully assembled with valves, springs, seals and retainers
valvetrain	Includes cam shafts, lifters, rockers, belts and pulleys
Clutch Parts	Includes clutch kits, discs, covers and bearings
Other Components	Includes short blocks, oil and water pumps

located at the top of the engine block, connecting to each of the cylinder heads.

- An oil cooler is used to assist with bringing the oil to operating temperature.
- Direct ignition coils are fitted. The igniter and current control circuits are integrated.
- The lower hose is located on the thermostat housing, connecting to the lower section of the radiator. The thermostat is housed in the oil pan extension case. The oil pan is much smaller than previous model engines and contains a small magnet to collect metallic debris.
- Connections for the crankcase ventilation system are located at the top of the valve cover. Pressure is equalized from the right bank with a cross over tube.
- The new crank angle sensor, reluctor, and EGR pipe. The crank angle sensor and reluctor have

been moved to the rear of the crankshaft. The EGR pipe has a new design and is mounted on the left bank of the engine.

3.0 Liter Engine Disassembly

- Begin disassembly by unloading and removing the serpentine belt.
- Remove the fuel rail protectors from both sides.
- The lower alternator bolt must be backed out before the manifold can be removed.
- Remove the alternator, compressor and power steering pump.

Note: The compressor is equipped with a speed sensor that sends a signal to the ECM. If the compressor speed drops more than 20% compared to the engine speed, the ECM turns the compressor off through the a/c relay. The refrigerant must be evacuated before removing the sensor.

- Remove the crankshaft bolt cover, bolt and harmonic balancer. Use caution to avoid losing the O-ring that seals the crankshaft bolt cover to the harmonic balancer.
- Begin removing the outer cover bolts. Keep them organized to ease reassembly. The bolts must be removed in the proper sequence to avoid warping the outer case.
- The timing chain on the EZ-3.0 is designed to last the life of the engine. Proper engine oil maintenance is necessary to ensure its longevity. Two chains are used. Four (4) camshaft sprockets, one (1) crankshaft sprocket, two (2) idler sprockets and the water pump complete the timing chain routing.
- The timing chain is sprayed with oil from a jet located on the oil pump relief valve housing.


H-4 and H-6 Engine Service

Caution: the sprocket teeth are sharp. Use extreme care when working around or near them.


- The right bank camshafts are in a loaded state when the keyways are at 12:00. They must be unloaded in the proper way to prevent damage to the pistons and valves.
- Timing marks are located on the camshaft sprockets and the crankshaft sprocket. Marks and letters on the idlers are manufactures markings and are used only to establish which side faces outward. Do not use them to establish proper chain timing.
- The left bank camshaft sprockets are interchangeable when new. It is recommended they be returned to their original positions to maintain wear patterns after being used.
- The left timing chain is the longer of the two with 148 links. The right chain has 134 links.
- Turn engine clockwise to rotate it until the key ways of the cam sprockets are at the 12:00 position. Remove the right bank tensioner, chain and chain guides.
- Remove the left bank tensioner, chain and chain guides.

Note: Turn the crankshaft 90 degrees counter clockwise to reduce the chance of accidental damage to the pistons and valves in the event the camshafts suddenly unload.

- The left bank is currently unloaded. The right bank is loaded and must be unloaded using the following procedure.




3.0 Liter Engine Timing Chain Routing



3.0 Liter Engine Right Bank Timing Components

Unloading Cam Sprockets

- Position the camshaft sprocket wrench on the right bank intake sprocket and turn 90 degrees counter clockwise.
- Position the camshaft sprocket wrench on the right bank exhaust sprocket and turn 90 degrees clockwise. Both camshafts are now unloaded.
- Remove both the intake and exhaust camshaft sprockets on the left and right banks.
- Remove the bolts from the water pump.
- Thread two eight millimeter bolts as shown and equally turn them in. This will assist with the removal of the pump. Remove the O-ring that seals the water pump to the inner cover.



3.0 Liter Engine Valvetrain

Valvetrain Construction

The camshafts are composed of carbon steel pipes with sintered metal lobes. During construction, the lobes are positioned on the pipe using a sintered metal paste. The camshafts are then baked until the paste is hardened. The lobes of the camshafts are offset by 1 millimeter to rotate the camshaft



Original Equipment Parts/
Professional Service

Genuine SUBARU AUTOMOTIVE CHEMICALS



...provide protection and enhance performance.

When it comes to fluids and other chemicals you put in a car, there's only one way to be sure you're meeting the same high standards of original Subaru equipment: Use Genuine Subaru Automotive Chemicals. You've got a full line of essential service chemicals to choose from, including aerosols, fluids and refrigerant. In fact, Subaru approves all of these premium chemicals for use in Subaru vehicles. Each automotive chemical is engineered to help assure maximum performance and trouble-free driving. Even the refrigerant is meticulously controlled for contaminants that can harm compressors. What's more, because Subaru Automotive Chemicals are competitively priced, you can use them regularly on all your service work.



Genuine Subaru Automotive Chemicals

Aerosols	Includes chlorinated and non-chlorinated brake and carburetor cleaners, aerosol and pour fuel injector cleaners, top engine cleaner, application tools and adapters, glass cleaner, throttle plate cleaner and silicone lubricant
Fluids	Includes factory fill coolant, brake fluid, factory fill windshield washer concentrate and automatic transmission fluid/power steering fluid
Refrigerant	Packaged to the ARI 700 Standard

bucket and shim, to reduce wear.

The right bank intake camshaft has a reluctor built onto the end. The new camshaft sensor uses this reluctor to help determine injection and ignition timing.

The valve adjustment procedure is the same as other DOHC Subaru engines however a new tool has been designed to work specifically on the EZ-3.0 engine. The tool is a wedge fitted into place over the two shims requiring removal.

Some adjustment will be required to properly seat the bucket depression finger. Turning the top bolt pushes the fingers down allowing room for the shim to be removed.

Chain Tensioners

The chain tensioners are fed oil pressure from the engine oiling system. The supplied pressure combined with spring tension



3.0 Liter Engine Chain Tensioners

keeps the timing chains operating at the correct tension.


Note: The left bank and right bank tensioners are not interchangeable.

The worm gear assemble and spring tension keep tension on

the chains with the engine off, eliminating any tension problems that could occur during engine start up. The tensioners are turned in by hand for reassembly. Observe the order of the worm gear assemble. Make sure your hands are dry when depressing the tensioners. A rivet or large paper clip will hold tensioner in place. Do not use a press to depress the tensioner.

Oil Pan Removal

- Remove the oil pan bolts and oil pan. Observe that the oil pan has a different design from four cylinder Subaru engines. Note the placement of the bolts.
- Remove the oil pan extension housing bolts. There are 28 bolts with five different lengths. Follow the proper sequence to prevent warping the case. Confirm the O-ring placement.



WRX Turbo Tech

The EJ-2.0 engine is a double overhead camshaft engine equipped on all turbocharged Impreza vehicles. The timing belt procedure and routing is very similar to other Subaru DOHC engines, however, the increased power output of the engine requires the use of an additional timing belt idler pulley. Manual transmission vehicles are equipped with additional belt guides that function during deceleration or fuel cut from high rpm running conditions. When servicing the timing belt return all idler pulleys and belt guides to their original positions.

The left bank intake camshaft sprocket is metallic and the camshaft reluctor is built into the backside. The timing marks for belt installation are at 12:00 (I) and 6:00 (II).

The left exhaust sprocket is made of a resin material. Its timing marks should be at 12:00 (II) and 3:00 (I) during belt installation. The exhaust 12:00 (II) mark lines up with 6:00 (II) of the intake sprocket. (A timing belt guide is located at the lower left side of the sprocket of manual transmission models.)

The right intake sprocket is also made of a resin material. During belt installation, its timing marks should be at 12:00 (I) and 6:00 (II). A timing belt guide is located at the upper left side of the sprocket of manual transmission models.

Finally, the right exhaust sprocket is made of a resin material. Its timing marks during belt installation should be at 9:00 (I) and 12:00 (II). The exhaust 12:00 (II) mark lines up with 6:00 (II) of



Left Bank Intake Cam Sprocket Timing Marks

the intake sprocket. A timing belt guide is located at the lower left of the sprocket on manual transmission models.

The engine class number is located near the front of the engine, behind the oil-sending unit and in front of the engine coolant temperature sensor.

A coolant pipe sealed with a


rubber plug is installed at the factory. Do not remove the plug to service any part of the cooling system.

The EJ-2.0 valvetrain is the same design used on other Subaru DOHC engines. A new shim tool has been developed to allow valve adjustment without removing the camshafts. However, the camshaft inner cover, camshaft sprockets and camshafts must be removed to access the cylinder head bolts.

The rear of the right bank cylinder head serves as the mounting point for the oil and coolant return passages for the turbocharger.

Tumble Generator Valve

The EJ-2.0 engine is equipped with a tumble generator valve at each intake runner. This new system uses a shaft for each side of



Intake Tumble Generator Valve

the shaft is monitored by a sensor on the opposite end.

The shaft operates the tumble generator valve, which is a plate similar in design to the throttle plate. At idle the plate is closed (depending on coolant temperature and time from engine start). Off idle the plate is open.

When the plate is closed the

Inner C.V. Joints

All inner constant velocity (C.V.) joints are remanufactured to ensure OEM quality and performance.

Shafts

All shafts are inspected to be straight and free of damaged splines.

New Ball Bearings


New Nuts included on all applications.

New Premium Grade Boots

Outer C.V. Joints

Outer constant velocity (C.V.) joints are remanufactured to ensure OEM quality and performance.

All threads are chased and seal surfaces are polished.



New Roll Pins

New Stainless Steel Boot Clamps

Flawless

Fit . . . Finish . . . and Performance!

Why take chances with inferior aftermarket axles that may have damaged threads, collapsed clip rings or smashed ends? Genuine Subaru front wheel drive axles are remanufactured using the industry's latest machine technologies. High quality components, plus rigorous final inspection and testing assures a replacement axle that installs quickly and performs flawlessly. Competitive pricing and the Genuine Subaru Parts Limited Warranty provide value and protection to you and your customers.

Be sure your customers get the best.
Call your local Subaru dealer to place your order now.

Remanufactured by



for



WRX Turbo Tech

main air passage through the intake runner is blocked. This will force all air necessary for engine operation during idle to flow through the bypass channel. This action helps to mix the air fuel mixture by producing a tumbling effect to the incoming air, resulting in a cleaner operating engine while idling.

The new fuel injector is a top feed type with 12 holes. The new hole pattern produces a finer spray of fuel which assists with lowering the overall emission output of the vehicle. (No air assist on Turbo models.)




Fuel Injector

Turbocharger

The introduction of the 2.0 liter engine to the US market reintroduces the turbocharger, which was last used on the 1994 Legacy 2.2 liter. The new turbocharger and fuel system have been designed to produce higher engine performance and lower exhaust emissions.

The turbocharger consists of two sections: an exhaust side and an induction side. The exhaust side has a turbine wheel with vanes that are shaped to harness the exhaust gas energy. This drives the turbine and center shaft. On the induction side, an impeller wheel is attached to the center shaft. It also has vanes, but they are shaped in the opposite direction.

The movement of the wheel compresses the induction air as it rotates. Increasing engine speed and load increases the level of kinetic energy in the exhaust gas, making the turbine rotate faster. This causes the impeller, which is attached to the common center shaft, to also rotate faster, creating




Turbocharger Cross-Section

greater compression of the induction air. Rotational speeds of the turbine are in the range of 20,000 rev/min. at idle, to 150,000-200,000 rev/min. at full power. These very high operating speeds and temperatures make lubrication and cooling of the center shaft bearings of prime importance.

The shaft bearings are lubricated by a constant supply of engine oil. An oil cooler positioned above the oil filter transfers heat from the oil to the engine coolant. Further cooling of the turbocharger is achieved by coolant fed from the right cylinder head to coolant passages around the exhaust turbine bearing.

There is a limit to the amount of boost pressure that can be used, due to the engine's design capabilities. The boost pressure is limited by a wastegate, which bypasses the exhaust gas around the turbine wheel when the desired level of boost is reached.



Wastegate

The ECM references a boost pressure map programmed into read only memory (ROM) after first reading the input signals. By calculating the actual boost pressure, and after compensating for engine temperature and atmospheric pressure, the ECM is able to provide an output duty ratio signal to the wastegate control solenoid. This regulates the amount of pressure applied to the wastegate controller diaphragm by leaking off boost pressure to the inlet side of the turbine.

The wastegate controller (in response to the duty solenoid) opens the wastegate flap valve to bypass exhaust gas and so decrease the rotating energy of the turbine keeping the boost pres-



Wastegate Control Solenoid

sure to the desired level.

When operating at increasing altitudes, the atmospheric pressure becomes lower and therefore the difference between the desired level of boost pressure and atmos-

pheric pressure becomes greater. To maintain the same level of boost pressure the air must be compressed more which requires more turbine rotating energy. Therefore less boost pressure is applied to the wastegate controller via the solenoid valve and boost remains constant.

However, at very high altitudes the extra compression of the air at maximum boost causes a too high intake air temperature even after intercooling and engine knock will occur. Therefore it is necessary to decrease the maximum boost pressure at very high altitudes.

Turbocharger Testing - Wastegate Control

Attach a regulated pressure sup-



THE GENUINE WAY TO STOP A SUBARU!

REMANUFACTURED CALIPERS OF THIS QUALITY CAN ONLY COME FROM SUBARU AND AKEBONO.

Not all remanufactured brake calipers are the same. Akebono remanufactured calipers for Subaru begin with original equipment. Then, Akebono assembles and tests calipers using materials and processes that meet or exceed Subaru specifications.

- ▶ ASSEMBLED IN A DUST-FREE ENVIRONMENT TO PREVENT CONTAMINATION.
- ▶ AKEBONO IS THE EXCLUSIVE PROVIDER OF GENUINE SUBARU REMANUFACTURED BRAKE CALIPERS.
- ▶ NO COMPROMISE IN SAFETY OR QUALITY FOR YOUR CUSTOMERS.

WRX Turbo Tech



Wastegate Valve Inside Turbo Housing

components in the boost control system, be sure that the wastegate is operating correctly.

Utilizing a dial gauge, measure the radial movement of the turbine shaft by accessing it through the oil outlet hole. Radial play should not exceed 0.17mm (0.006 inches).

To measure the axial movement of the turbine shaft, place the dial gauge against the end of the shaft at the turbine end, and push against the compressor end of the shaft. Axial play should not exceed 0.09mm (0.003 inches).



Turbocharger


Intercooler

The turbocharger compresses the intake air by using wasted exhaust gas energy. The turbocharger turbine is driven by exhaust gas, causing the compressor wheel to rotate. By compressing the intake air, the volumetric efficiency of the engine is greatly improved.

The compression of the intake air by

the turbocharger causes an increase in air temperature, so an intercooler is located between the turbocharger and the intake manifold. The intercooler reduces the temperature of the intake air from 248-266° F (120-130° C) down to 158-176 F° (70-80° C) under normal operating conditions.

An air bypass valve redirects high pressures from the intercooler back to the inlet side of the turbocharger under deceleration.



Turbocharger Bearing Testing

The temperature of the intake air is increased as it is compressed by the turbocharger. This rise in temperature causes a corresponding expansion of the air, leading to a reduction in air density. The intercooler is designed to transfer the heat of the compressed intake air to the external air flowing through as the vehicle is in motion.




Intercooler

There are two positive byproducts of decreased air temperature and

increased air density: one; a reduction in combustion chamber temperature allowing for more advanced ignition timing, and two; improved volumetric efficiency due to the increase in air mass for a given air volume. With a denser air charge into the combustion chamber, more fuel can be injected, leading to greater power output.

The air bypass valve is located after the turbocharger, and provides a bypass passage for the compressed intake air back to the inlet side of the turbocharger. When deceleration occurs immediately after a period of high engine load (high boost pressure), a large pressure differential occurs at the compressor wheel of the turbocharger. This is due to the inertia of the turbocharger, which still generates boost pres-

sure even though the throttle is fully closed. This high pressure may lead to increased



Effects of Intercooler

noise, and possibly damage the turbocharger due to the high pressure exerted at the compressor.

The upper chamber of the bypass valve is connected to the intake manifold, and the negative

pressure (vacuum) during deceleration opens the valve by acting on the diaphragm.

Operation of the valve can be tested by attaching a hand held vacuum pump to the intake manifold connection. Apply a negative pressure with the pump and confirm that the valve opens.

Ambient Air Temperature and Pressure

As air temperature rises, the ability of the turbocharger to compress the air decreases. This phenomenon is directly due to the decrease in air density and the physical limitation of the turbocharger. Even when air temperature is low, the air density (barometric pressure) may be low. Under these conditions, lower than expected boost pressures may be experienced. Again this is

They're Rugged, They're Heavy Duty, They're Built to Last.



Genuine Subaru Remanufactured Starters

- Perform like new parts
- Provide exact replacement and fit
- Ensure long term reliability
- Backed by same warranty as new parts

SUBARU 
Genuine Parts

Remanufactured for Subaru by

DENSO

Available only through your local SUBARU dealer

WRX Turbo Tech

due to the physical limitations of the turbocharger.



Intercooler Interior

Exhaust Diameter

The diameter of the exhaust system will vary the pressure difference across the turbine. A larger exhaust allows the turbocharger to rotate faster, which results in higher boost pressures. Any increase in boost pressures would require 're-mapping' of the ECM programs to accommodate different air flow rates and resultant ignition change requirements. Over speeding of the turbine can lead to turbocharger failure, particularly in conjunction with the increase in the pressure differential across the turbine.




Intercooler Air By-Pass Passage

Fuel Octane Rating

The high combustion pressures resulting from the increase in volumetric efficiency require a high-octane fuel. If the octane of the fuel is too low, knocking will occur. The end result of

knocking is damage to the engine. The ECM is programmed to retard ignition timing if knocking is detected. Excess knocking will cause the ECM to enter a 'Fail-safe' mode where the boost pressure is reduced to the minimum value determined by the wastegate actuator.

Air By-Pass Valve Operation



Air By-Pass Operation

Turbo Lag


The pressure of the exhaust gas is low at low engine speeds. As the turbocharger uses exhaust energy to operate, it does not respond immediately when the throttle is opened. This phenomenon is referred to as 'turbo lag.' In an attempt to overcome this phenomenon, design characteristics of the turbocharger are matched to the prospective use of the vehicle.



Turbocharger Outlet Hose Clamp

Turbocharger Removal

Turbocharger removal is accomplished by first removing the intercooler mounting bracket. Then remove the eight bolts that secure the protective



Turbocharger Mounting Bracket

heat shield around the turbo.


Raise the vehicle and disconnect the rear oxygen sensor harness and remove the front exhaust pipe mounting bolt. Position the pipe so that there is some movement. Lower the vehicle and disconnect the wastegate hose to the vacuum hose leading to the wastegate control solenoid. Remove the coolant hose from the reservoir that con-

nects to the turbo.

Disconnect the turbocharger outlet hose clamp and the small metal bracket that connects the cylinder head to the base of the turbocharger (strengthens the upper portion of the cross over pipe). Loosen the oil supply metal pipe at the cylinder head. Remove the banjo bolt and secure the copper washers from the top of the turbocharger. Gently pull the oil supply metal pipe away from the turbocharger.

Place a shop towel between the turbocharger and the engine and remove the two banjo bolts that secure the coolant supply and return hoses. Catch the copper sealing washers (two per bolt) or find them in or on the shop towel. Remove the shop towel.

Remove the five bolts that secure the turbocharger outlet to



Turbocharger Mounting Flange

the exhaust and slide the pipe back to clear the studs. Remove the gasket at this time.

Remove the three nuts that secure the turbocharger to the cross over pipe and secure the gasket (inlet). Remove the turbocharger from the engine compartment and cover all opening in the exhaust and on the turbocharger.

Bosal gives you genuine Subaru quality.

Bosal direct-fit exhaust systems are genuine Subaru OEM Service Parts. And when we say direct fit, we mean direct fit! No cutting, bending, or welding means faster and better installations. When you choose Bosal Exhaust, you'll get the fit, performance, and durability your customers expect.

Bosal Performance Exhaust

Available exclusively through the Subaru Dealer Network. Bosal Performance Mufflers with high-flow capacity, high performance sound, and oversize polished stainless steel tips. For Impreza RS Coupe and **Legacy GT Sedans and Wagons.**

bosal

Bosal Exhaust for Subaru. Available through your local Subaru Dealer.

insider info.

WRX Turbo Cool Down Procedure

It is not necessary to perform a “cool down/idling” procedure on Subaru WRX turbo models, as was recommended with past turbo models. “The current 2.0 liter turbo engine has a far greater cooling capacity and, coupled with technology advances, makes this practice no longer necessary. This explains why information about a cool down is not included in the Impreza Owner’s Manual.

The heat contained in the turbocharger begins to vaporize the coolant at the turbocharger after the engine is stopped. This hot vapor then enters the coolant reservoir tank, which is the highest point of the coolant system. At the same time the vapor exits the turbocharger, coolant supplied from the right bank cylinder head flows into the turbo. This action reduces the turbocharger temperature. This process will continue until the vaporizing action in the turbocharger has stopped or cooled down.



WRX 2.0 Liter Turbocharger

Three Bond Sealer

The Subaru H-6 engine timing chain cover is sealed with Three Bond 1280B sealer. Subaru of America has located a source this sealer in the U.S. The sealer should be ordered from your Subaru parts department under part number S0A5499100. One tube can be used for approximately seven engines.

If you are working on an H-6 that requires this sealer, be sure to use Three Bond 1280B and not Three Bond 1215.

Knocking Or Tapping Noise: 2.5 Liter Engine

Before condemning a 2.5 liter engine for having an engine knock or a valve tap, make certain that all the spark plug wires are firmly connected to their corresponding spark plugs. The spark plugs are deeply recessed in the cylinder heads, so the sound that is produced by a loose plug wire can easily be confused with valve tap or piston slap.

Engine Noises

Engines in some 1997 and later Subaru vehicles have been fitted with solid valve lifters. These lifters help increase the power of the engines. Some of these engines use a lifter setup that requires the use of a shim to adjust the clearance. A characteristic of this setup is a slight tapping noise, heard especially at idle. The intensity of the noise may vary with engine temperature. Typically, this noise is not apparent in the passenger compartment. No attempt should be made to repair this noise because it is a characteristic of the system.

Assembling 1997 And Newer Engines

When assembling 1997 and newer engines, please remember that on vehicles with non-hydraulic lifters, special precautions must be taken to ensure that no valves are bent during the assembly process. There is no longer any clearance between a fully opened valve and a piston near top dead center. This means that you must position the crankshaft and the camshafts properly before installing the cylinder heads. After the head is in place, do not turn the crank or move the cams in the wrong directions.

Before installing the heads, the crankshaft should be positioned with the crank sprocket aligned with the mark on the block. The camshafts should be installed on the heads with the cam lobe in their “zero lift” position. On the passenger’s side head, this position will be the same as the belt installation position, so position the cams that way prior to bolting them to the head. On the dri-

ver's side head, however, this position is approximately 80 degrees counterclockwise from the belt installation position for the intake cam and approximately 45 degrees clockwise from the belt installation position for the exhaust cam. So hold the cams appropriately while bolting them to the head. After the cylinder heads are installed, the cams can carefully be aligned with their corresponding marks by rotating the driver's intake cam 80 degrees clockwise and the driver's exhaust cam 45 degrees counterclockwise.

Oil Pumps: Replacement Versus Resealing

When diagnosing a leaking oil pump, don't automatically replace it with a new pump

when a simple reseal will do. The only time a pump should be replaced is if the housing is porous, cracked, or damaged in some other manner.

Valve Shim Measurement

Several Subaru engines use shims to adjust valve clearance. If you don't have a micrometer, acquire one that is calibrated in millimeters. Even though the service interval for adjusting the valves is 100,000 miles, there are 16 of them per four-cylinder engine, so proficiency is a plus.

Leaking Front Crankshaft Oil Seals

If you encounter a 2.5 liter engine with a leaking or dislodged front crankshaft oil seal, consider the oil pump as a possi-

ble cause. It may be necessary to remove the oil pump and examine the rear sealing plate of the oil pump. The screws holding the rear sealing plate may be loose. Some have been reportedly backed out 1/16-inch. This allows oil to exit the pump rotor area and get into the oil pump body where it is pressurized. This pressurized oil pushes on the seal, causing it to leak or pushes it out of its mounting.

Oil Leaks

The engine oil and automatic transmission fluid used in Subaru vehicles are similar in color. When diagnosing an oil leak and it has a reddish color, don't automatically assume it is automatic transmission fluid. It might be engine oil. A quick way to find

Continued on page 30.

Search over 50,000 pages of information with just a few clicks... and leave your books behind.

As any tech knows, the most powerful tool you can have working on your side is knowledge. And with the volumes of information available on Subaru vehicles, you need an easy to use, fast solution that will let you sift through all of that information to get what you need. That's where the Subaru Technical Information System (STIS) comes into play.

Whether you are looking for information on a 2001 Legacy Ignition Coil, or a 2004 Baja Reduction Drive Gear, the STIS web site has the service manual documentation you need.

But service manuals are only the beginning; we've filled the web site with Service Bulletins, Subaru TechTIPS,



Owners Manuals, Product and Service Campaign Bulletins, Technician Training Materials, and Warranty Bulletins just for starters.

Additionally, you will never have to worry about having the latest information on previous, as well as current, Subaru vehicles. That's because we are constantly updating the information on the site — updates that eventually come out in printed form, but wouldn't you rather have the latest information at your fingertips instead of sitting on a shelf somewhere in your shop?

So take a few minutes and check out the Subaru Technical Information System. You'll be glad you did.

<http://techinfo.subaru.com>

What is a

Subaru N.E.W. Horizons Dealer?

Subaru N.E.W. Horizons Dealers have been recognized for their outstanding performance in serving the wholesale market. N.E.W. Horizons dealers provide you with a direct wholesale parts hotline and also maintain a large inventory of competitively priced Genuine Subaru Parts, which means you can get most parts immediately. If not, the N.E.W. Horizons dealer's direct access to the Subaru Parts Distribution Network means it can get you almost any part you need quickly. If you have a question about a specific part or repair job, just ask. No one knows a Subaru, or the parts needed to repair them, like a Subaru N.E.W. Horizons Dealer.

Please note: Left column telephone numbers provide direct access to Subaru N.E.W. Horizons Parts Departments. Right column numbers provide general access to Subaru N.E.W. Horizons Dealers.

Alaska

Anchorage
Continental Motors
800.478.7278 907.562.2722

Arizona

Phoenix
21 Bell Subaru
602.493.6602 602.493.6600

Phoenix
Camelback Subaru
800.876.5199 602.265.6600

Scottsdale
Pitre Subaru
480.425.2950 480.425.2800

Tucson
Emich Subaru
520.298.3011 520.721.2400

Arkansas

Little Rock
Riverside Subaru
501.448.0042 501.448.8000

California

Albany
Albany Subaru
510.526.8791 510.528.1244

Auburn
Gold Rush Subaru
800.995.2438 530.885.4019

Carlsbad
Bob Baker Subaru
760.431.3062 760.431.3000

El Cajon
Bob Baker Subaru
619.440.1213 619.440.0404

Fresno
Herwaldt Subaru
559.448.6934 559.438.6944

Fullerton
Renick Subaru
888.923.8201 714.871.9300

Lake Forest
Irvine Subaru
949.452.0100 949.837.3500

Livermore
Livermore Subaru
925.447.1173 925.447.1100

Long Beach
Timmons Subaru
888.489.5001 562.595.4601

Monrovia
Sierra Subaru of Monrovia
626.932.5678 626.359.8291

Oakland
Downtown Subaru
510.653.0350 510.547.4424

Ontario
Exclusively Subaru
909.605.5816 909.605.5800

Redding
Shasta Subaru
800.936.4772 530.223.2177

Redwood City
Carlsen Subaru
650.365.2600 650.365.6390

Roseville
Roseville Subaru
883.220.4269 916.786.6611

Sacramento
Maita Subaru
800.383.7278 916.486.8000

Sacramento
Senator Subaru
800.533.6567 916.427.1234

San Bernardino
Subaru of San Bernardino
888.378.2278 909.888.8686

San Diego
Balboa Subaru
888.409.7278 858.278.6074

San Jose
Stevens Creek Subaru
408.984.1006 408.984.2001

San Luis Obispo
Rancho Grande Subaru
805.543.4985 805.543.4745

San Rafael
Marin Subaru
415.257.4690 415.454.9240

Santa Monica
Santa Monica Subaru
866.761.5555 310.393.9881

Santa Rosa
Prestige Imports
800.773.1855 707.545.6602

Shingle Springs
Shingle Springs Subaru
800.345.7778 530.677.8771

South San Francisco
Ron Price Subaru
650.583.4040 650.589.9788

Thousand Oaks
Subaru of Thousand Oaks
805.371.5572 805.371.5555

Van Nuys
Big Valley Subaru
818.781.2785 818.787.0800

Colorado

Aurora
Shortline Automotive
800.332.1161 303.364.2200

Boulder
Flatirons Subaru
800.634.6621 303.443.0114

Colorado Springs
Heuberger Motors
800.675.2227 719.475.1920

Durango
Morehart Subaru
970.385.0202 970.247.2121

Englewood
Burt Subaru
800.525.8402 303.761.7453

Englewood
John Elway Subaru South
303.792.2201 303.792.0330

Fort Collins
Dellenbach Motors
800.426.7314 970.226.3100

Golden
John Elway Subaru West
303.590.6633 303.590.6600

Grand Junction
Rocky Mountain Subaru
800.244.2902 970.241.2414

Greeley
Ehrlich Subaru
970.346.3542 970.353.7707

Longmont
Valley Subaru
303.447.9531 303.776.0443

Thornton
Mike Shaw Subaru
800.640.5219 303.438.7500

Connecticut

Branford
Premier Subaru
800.411.4551 203.481.0687

Canton
Mitchell Subaru
800.782.2781 860.693.6391

Danbury
Colonial Subaru
800.229.2656 203.744.8383

Milford
Dan Perkins Subaru
800.367.9335 203.882.5680

New Britain
Schaller Subaru
800.382.4525 860.223.2230

Torrington
Center Subaru
800.423.7822 860.489.1301

Watertown
Chase Parkway Subaru
860.274.8866

Florida

Delray Beach
Delray Subaru
888.830.7337 561.276.7800

Gainesville
Palm Subaru
800.541.4011 352.372.2561

Jacksonville
Subaru of Jacksonville, Inc.
800.393.3455 904.641.6455

Miami
William Lehman Subaru
800.999.9118 305.653.7123

Sanford
Bob Dance Subaru
877.917.1792 407.323.7730

Tallahassee
Kelly Subaru
800.819.2893 850.575.6166

Tampa
Mastro Subaru
800.683.2532 813.884.7513

Winter Park
Bill Bryan Subaru of Winter Park
800.882.7926 407.628.4343

Georgia

Cumming
Troncalli Subaru
800.646.9438 770.889.8951

Decatur
Royal Subaru
800.445.0948 404.296.9100

Smyrna
Ed Voyles Subaru Inc.
770.933.5770 770.952.8881

Idaho

Boise
Larry Miller Subaru
888.941.2218 208.323.6300

Moscow
Ambassador Auto Services
800.422.0297 208.882.2722

Illinois

Countryside
Dan Wolf Subaru
708.354.6200 708.352.7800

Evanston
Evanston Subaru
847.869.9769 847.869.5700

Highland Park
Grant Dean Subaru
847.432.0708 847.432.4800

Joliet
Thomas Subaru of Joliet
815.741.5352 815.741.5353

Libertyville
Liberty Subaru
847.362.1644 847.362.2683

Lynwood
Lynwood Motors
708.758.3191 708.758.0120

Naperville
Gerald Subaru
630.355.8111 630.355.3900

North Aurora
Gerald Subaru North Aurora
630.907.0800 630.907.0800

Savoy
Worden Martin Subaru
800.523.0754 217.352.8910

Schaumburg
Subaru of Schaumburg
800.828.9899 847.884.6000

Indiana

Indianapolis
Speedway International
317.263.3742 317.263.0002

Indianapolis
Tom Wood Subaru
800.966.6056 317.848.8888

South Bend
Bill Frank Automotive
800.222.7089 574.277.5800

Iowa

Cedar Rapids
Jim Miller Subaru
800.332.0290 319.393.0640

Davenport
Lujack's Northpark Auto Plaza
800.553.8042 563.386.1511

Kansas

Olathe
Jack Miller Subaru Olathe
913.780.1484 913.780.0400

Topeka
Figgs Imports
800.757.7717 785.267.2390

Kentucky

Louisville
Bachman Subaru
866.897.8227 502.493.2920

Louisville
Neil Huffman Imports
800.777.6509 502.448.6666

Nicholasville
Oldham's Subaru
800.886.1777 859.885.3900

Maine

Bangor
Quirk Subaru of Bangor
800.281.1960 207.942.7364

South Portland
Maine Mall Subaru
800.640.6685 207.774.1429

Maryland

Annapolis
Annapolis Subaru
410.349.8186 410.349.8800

Baltimore
Russel Subaru
410.788.1700 410.744.2300

Cockeysville
Subaru of Hunt Valley
410.666.4194 410.666.7777

Cumberland
Thomas Subaru
888.724.6310 301.724.6310

Hagerstown
Sharrett Subaru, Inc.
301.739.9999 301.739.7700

Kensington
Fitzgerald Subaru
800.876.3748 301.881.4000

Owings Mills
Heritage Subaru
410.581.6696 410.363.8300

Silver Spring
Herb Gordon Subaru
800.926.3040 301.890.3040

Massachusetts

Arlington
Cityside Subaru
781.647.9999 781.641.1900

Danvers
Ira Subaru
800.774.8411 978.739.8200

Hanover
Planet Subaru
781.826.1103 781.826.4444

Lunenburg
North End Auto Sales
800.548.8887 978.582.4911

Norwood
Norwood Subaru
800.541.6122 781.762.2400

Shrewsbury
Patrick Subaru
800.344.7222 508.756.8364

Michigan

Ann Arbor
Ann Arbor Subaru
800.662.0073 734.662.3444

Bay City
Thelen Subaru
800.800.7158 989.684.2980

Commerce Township
Dwyer & Sons Subaru
248.669.7835 248.624.0400

Ferndale
Hodges Imports Cars
248.547.6167 248.547.8800

Kalamazoo
Maple Hill Subaru
616.342.7365 269.342.6600

Kentwood
East Subaru
800.678.1302 616.942.8040

Lansing
Williams Auto World - Subaru
800.258.2853 517.484.1341

Marquette
Crown Subaru
888.276.9642 906.226.1600

Traverse City
Cherry Capital Subaru
800.852.6475 231.947.9000

Troy
Suburban Subaru
248.643.0735 248.643.7660

Minnesota

Bloomington
Bloomington Subaru
800.451.5078 952.881.6200

Brooklyn Park
Brooklyn Park Subaru
952.797.1699 763.424.3331

Minnetonka
Morrie's Subaru
800.332.4266 952.544.0376

Moorhead
Ward Muscatell Subaru
800.373.8282 218.236.0191

Vadnais Heights
White Bear Subaru
651.481.3180 651.481.0230

Missouri

Ballwin
Dean Team Subaru
636.227.6527 636.227.0100

North Kansas City
Jack Miller Subaru
816.472.4522 816.474.3100

St Louis
Lou Fusz Subaru
800.341.5935 314.983.4400

Webster Groves
Webster Groves Subaru
800.966.5184 314.968.5167

Montana

Bozeman
Dick Walter Subaru
800.735.2834 406.586.1771

Missoula
Four Seasons Motors
800.800.6569 406.728.2510

Nebraska

Bellevue
Beardmore Subaru
800.228.9198 402.734.2525

Omaha
Stan Olsen Subaru
402.393.1989 402.397.8300

Nevada

Reno
Reno Subaru
800.495.6060 775.825.8474

New Hampshire

Hudson
Subaru of Nashua
877.567.4812 603.888.9999

New Jersey

Avenel
Richard Lucas Subaru
732.634.1900 732.634.0100

Bloomfield
Lynnes Subaru
973.743.8387 973.743.2111

Cherry Hill
Cherry Hill Subaru
856.661.8960 856.663.1500

Flemington
Flemington Subaru
888.328.2568 908.782.2025

Morristown
Subaru of Morristown
800.541.1127 973.326.9131

Oradell
Liberty Subaru
201.261.7495 201.261.0900

Sicklerville
Martin Subaru
800.288.8756 856.629.6833

New Mexico

Albuquerque
Galles Davis Subaru
505.837.5139 505.837.5200

Albuquerque
Garcia Subaru
505.760.5164 505.260.5155

Santa Fe
Premier Subaru of Santa Fe
505.428.7341 505.471.7007

New York

Amherst
Northtown Subaru
716.835.4611 716.835.8500

Brewster
Smith Cairns Subaru of Brewster
845.278.8300 845.278.8300

Brooklyn
Beltway Buick Subaru
718.232.1919 718.234.7960

Colonie
Goldstein Subaru of Albany
800.955.1727 518.869.1250

Glen Cove
North Coast Subaru
516.770.7333 516.676.3676

Hicksville
Grand Prix Subaru
516.822.2200 516.822.6800

Huntington
Metric Auto Sales Inc.
800.696.9980 631.499.6777

Ithaca
Bill Cooke Imports, Inc.
800.870.3270 607.257.1515

Jamestown
Ed Shults Subaru
800.752.7774 716.484.7151

Kingston
Colonial Motor Cars Ltd.
845.339.7895 845.339.3330

Orangeburg
Bill Kolb Jr. Subaru Inc.
845.398.6323 845.359.7777

Orchard Park
West-Herr Subaru
716.662.3570 716.662.3565

Patchogue
Brown's Subaru
631.289.8505 631.289.8500

Pleasantville
Prestige Imports
800.769.4611 914.769.5100

Ravena
Marshalls Auto Exchange Inc.
518.756.9701 518.756.6161

Rhinebeck
Ruge's Subaru
800.343.7843 845.876.7074

Riverhead
Riverhead Bay Motors
631.727.5590 631.727.4000

Rochester
Piehler Subaru
585.254.4754 585.458.4540

Rye
Rye Subaru
914.967.4830 914.967.6300

Syracuse
Bill Rapp Subaru
315.437.0198 315.437.2501

Syracuse
Romano Subaru Inc.
315.475.3365 314.475.7933

Utica
Don's Subaru
800.527.1027 315.797.1520

Vestal
Matthews Subaru Company
607.754.0397 607.754.2050

Victor
Van Bortel Motorcar Inc.
585.924.4383 585.924.5230

Wappingers Falls
Wappingers Falls Subaru
845.298.4465 845.298.8880

Yonkers
Smith-Cairns Subaru
914.377.8116 914.377.8100

Yorktown Heights
Curry Subaru
800.288.6777 914.736.1300

North Carolina

Asheville
Prestige Dodge Subaru, Inc.
888.854.4293 828.298.9600

Boone
Southern States Subaru of Boone
800.844.2665 828.264.0675

Chapel Hill
Performance Subaru
800.476.3191 919.942.3191

Charlotte
Folger Subaru
800.376.1242 704.536.9635

Greensboro
Bob Dunn Ford-Subaru
800.489.3866 336.275.9761

Hendersonville
Hunter Motors
800.968.8660 828.693.8661

Hickory
Jim Armstrong Subaru
800.650.6121 828.322.9372

Raleigh
Southern States Imports, Inc.
800.489.3684 919.828.0901

Winston Salem
Flow Subaru
800.467.5002 336.723.3524

Ohio

Cincinnati
Jake Sweeney Subaru
888.489.5253 513.489.5253

Cincinnati
Subaru of Beechmont
513.474.5720 513.474.4313

Columbus
Byers Imports
614.552.5490 614.864.5180

Columbus
Byers Subaru
614.792.2462 614.792.2455

Columbus
Hatfield Subaru
614.675.0288 614.870.9559

Fairborn
Wagner Auto Sales
866.243.2171 937.878.2171

North Olmsted
Ganley Westside Imports
440.734.1076 440.734.2000

Warrensville Heights
Ellacott Shaker Subaru
800.475.8555 216.475.3444

Wickliffe
Ganley Subaru East
800.634.9770 440.585.1000

Oklahoma

Broken Arrow
Ferguson Advantage Imports
800.880.8815 918.258.1800

Oklahoma City
Cable Motors
405.787.0095 405.787.0433

Oregon

Beaverton
Carr Subaru
800.405.9808 503.644.2161

Eugene
Kendall Subaru
541.465.3555 541.465.4600

Gresham
Gresham Subaru
800.669.1198 503.661.1200

Medford
Southern Oregon Subaru
800.866.9756 541.772.3377

Oregon City
Lithia Subaru of Oregon City
866.717.2512 503.656.0612

Portland
Wentworth Subaru
800.232.8097 503.232.2000

Pennsylvania

Allentown
Becker Subaru
610.395.6530 610.395.3745

Butler
Kerven Enterprises, Inc.
800.KERVEN9 724.287.0734

Concordville
Concordville Subaru
800.220.3100 610.459.8900

Doylestown
Fred Beans Subaru
215.348.0202 215.348.7500

East Petersburg
Lancaster County Motors Subaru
800.215.5644 717.569.4514

Erie
New Motors, Inc.
800.352.1052 814.868.4805

Feasterville
Colonial Subaru
215.355.8856 215.355.8800

Jenkintown
Glanzmann Subaru
800.440.0130 215.885.8282

Leesport
Steve Moyer Subaru
800.995.2627 610.916.7000

Limerick
Welsh Subaru of Limerick
610.489.4198 610.489.3122

Mechanicsburg
Cumberland Valley Motors
800.382.1436 717.697.9448

Monroeville
Langston Subaru
877.563.4937 724.325.2888

Moosic
Minooka Subaru
800.982.4054 570.346.4641

Newtown Square
Rafferty Subaru
610.353.6906 610.353.6900

Northumberland
W & L Subaru
877.995.7822 570.473.3432

Philadelphia
Wilkie Subaru
800.962.4389 215.236.7500

Pittsburgh
Bill Gray Subaru
412.344.0181 412.344.0100

Pittsburgh
Bowser Subaru
800.231.4452 412.469.2100

Stroudsburg
Ertle Subaru
570.213.4035 570.421.4140

York
Apple Subaru
800.228.7299 717.854.1800

Rhode Island

Warwick
Bald Hill Subaru
401.822.8110 401.822.8100

South Dakota

Sioux Falls
Lithia Subaru of Sioux Falls
605.330.0471 605.333.0198

Tennessee

Bristol
Wallace Subaru
800.652.6882 423.764.1145

Harriman
Earl Duff Subaru
877.610.2005 865.882.0113

Nashville
Jim Reed Subaru
800.522.2207 615.329.2929

Texas

Arlington
Arlington Auto Mall
817.265.7278 817.861.3377

Austin
Austin Subaru
800.385.4076 512.454.9489

Austin
Gillman Subaru
800.955.3980 512.444.6044

Houston
Gillman Subaru
800.999.8309 713.776.6310

Houston
West Houston Subaru
281.676.2155 281.398.3300

Lewisville
Huffines Subaru
800.650.6261 972.221.8686

Plano
Central Subaru
972.422.9320 972.422.5300

San Antonio
North Park Subaru
800.880.8846 210.308.0200

Utah

Salt Lake City
Mark Miller Subaru
800.348.8207 801.268.3734

Salt Lake City
Nate Wade Subaru
800.221.4287 801.355.7571

Sandy
Larry H. Miller Subaru
800.453.6456 Ext. 2 801.553.5200

Vermont

Rutland
Kinney Subaru
802.775.6900

Virginia

Alexandria
Beyer Subaru
703.660.1234 703.768.5800

Charlottesville
Brown Subaru
800.635.3170 434.977.3380

Fairfax
Farrish Subaru
703.934.1620 703.273.0200

Harrisonburg
Bob Wade Subaru
540.434.1892 540.434.3900

Leesburg
Dulles Subaru
703.777.7077 703.777.7077

Lynchburg
Terry Subaru
800.964.5516 434.239.2601

Midlothian
Pence Subaru
800.447.3623 804.378.3000

Newport News
Casey Imports, Inc.
757.988.1275 757.988.1200

Roanoke
First Team Subaru
800.277.8757 540.366.4830

Springfield
Subaru Springfield, Inc.
703.451.2389 703.451.7799

Staunton
Staunton Subaru
800.296.3465 540.886.3465

Vienna
Stohlman Subaru
800.697.4979 703.893.2990

Washington

Auburn
Auburn Subaru
800.827.2787 253.737.1345

Bellevue
Chaplin's Bellevue Subaru
800.962.0822 425.641.2002

Bellingham
Dewey Griffin Subaru
800.846.1549 360.734.8700

Bremerton
Peninsula Subaru
800.458.5808 360.479.4320

Kirkland
Eastside Subaru
800.861.9118 425.820.8993

Puyallup
Subaru of Puyallup
800.598.5134 253.445.8255

Renton
Walker's Renton Subaru
800.261.7366 425.226.2775

Seattle
Carter Subaru
800.562.1314 206.542.1166

Spokane
Appleway Subaru
800.876.4412 509.924.6900

Spokane
Camp Subaru
800.776.9946 509.458.3288

Tacoma
Tacoma Subaru
888.473.6200 253.473.6200

Vancouver
Hannah Subaru
503.252.9947 360.314.0505

West Virginia

Fairmont
Larry Myers Subaru
304.366.4476 304.366.3311

Morgantown
John Howard Motors
800.999.9194 304.296.3205

Wisconsin

Appleton
Gustman Motor Company
800.283.6693 920.733.6693

Madison
Don Miller Subaru
800.362.3323 608.258.3500

Mequon
Sommer's Subaru
888.820.0608 262.242.0100

Schofield
Dave Kasten Motors
715.359.2637 715.359.3638

Waukesha
Don Jacobs Subaru
800.334.3934 262.542.5711

Wyoming

Cheyenne
Dinneen Subaru
888.634.7733 307.778.2410



NEW

NATIONAL • EXPANDED • WHOLESALE

HORIZONS

Please note: Left column telephone numbers provide direct access to Subaru N.E.W. Horizons Parts Departments. Right column numbers provide general access to Subaru N.E.W. Horizons Dealers.

insider info.

Continued from page 25.


out is to take a sample of the oil and place it on a clean white paper towel. If the sample turns brown on the paper towel, it is engine oil. If it stays red, it is automatic transmission fluid.

Oil Filters: H-4 Versus H-6 Engines

Subaru H-4 engines come from the factory with an OEM P/N 15208AA060 oil filter. The same part number is used for replacement. H-6 engines come with an OEM P/N 15208AA031, and SOA5165109 is used as a replacement.

Both filters have the same physical dimensions as far as threads, O-ring, and bypass valve opening pressure (23 p.s.i.) are concerned. However, the H-4 filter has 141 square inches of filtration surface, while the H-6 filter has 201 square inches of filtration surface.

The H-4 filter should not be used on the H-6 engine. Using the H-4 filter may cause it to become contaminated faster and allow the bypass valve to open, allowing unfiltered oil to circulate through the engine.




H-6 Engine On Stand w/Oil Filter

Cold Engine Noises

Beginning with the 1997 model, the 2.2 and 2.5 engines were made more fuel efficient, more powerful and have a flatter, more usable torque curve than in previous years.


Some of these engines may exhibit some engine noise during the warm-up period after a cold start-up. This noise is a consequence of the engine improvements and is not, in any way, an indication of any engine problem. A light engine knock, after cold start, that gradually dissipates as the engine warms up and is virtually

undetectable (from inside the vehicle) once the engine has reached operating temperature, is a normal characteristic of these engines. Repair attempts to reduce this type noise are generally unsuccessful.



Checking Oil Level and Quality

If you have a vehicle in which an engine noise is other than that as described above, be sure to take the time to check all possible causes prior to condemning the internal components of the engine. Before replacing parts in an attempt to eliminate engine noise, the engine should be inspected externally and internally for another source of noise. A look at the engine oil is a good place to start. New engines will have a small amount of metal particles in them, but after that should be relatively free of metal.



Timing Belt, Idlers and Tensioner

Another area to look at would be the timing belt tensioner and the belt and sprockets. There have been cases where noises under the belt covers and from external components have made noises that sounded like a deep internal knock.

NGK *IRIDIUM*



What Performance Looks Like

Drive On! Get behind the wheel and go.

NGK Iridium Spark Plugs. *It's in the Tip.*

*NGK Iridium spark plug technology is OE on the Subaru WRX STI.
NGK is the exclusive supplier to Subaru of America for all
replacement spark plug applications.*

www.ngksparkplugs.com



THE WORLD LEADER

IF YOU WANT IT NOW, THINK N.E.W.



❖ N.E.W. ❖ NATIONAL • EXPANDED • WHOLESALE HORIZONS

N.E.W. for National Expanded Wholesale—check the listing inside to find a participating dealer!

Looking for a Subaru parts supplier with better service, faster delivery, deeper inventory, and more competitive pricing? Check the listing inside this issue to find a N.E.W. Horizons Subaru dealer near you.

Looking for a Subaru parts supplier with better service, faster delivery, deeper inventory, and more competitive pricing? Check the listing inside this

This national network of high-performing Subaru dealers is dedicated to meeting the wholesale parts needs of independent repair shops like yours:

- Large inventory of Genuine Subaru Parts
- New and remanufactured parts at prices competitive to rebuilt
- Technical and application advice
- A Hotline providing direct access to parts inventory



Original Equipment Parts/
Professional Service

PRST STD
U.S. POSTAGE
PAID
Cleveland, OH
Permit No. 1535