Topology Diagnostics

More evidence that the PCM is probably not the problem, and an ethical dilemma

was called to a shop to program a new Powertrain Control Module on a 2007 Jeep Grand Cherokee (Figure 1). The shop diagnosed the Jeep and made the decision to purchase a new PCM to resolve a nostart situation. Reprogramming has become a common practice for me these days because a lot of shops do not want to get involved with the procedure. It may be due to costly subscription fees or just the liabilities involved when programming a controller. If you don't know what you're doing, or are just not careful enough you could be the proud owner of a new or rebuilt computer. So, sometimes it may be easier for a shop owner to hire my company for these services.

I arrived at the shop and plugged in the old contoller first to read software information about the module so that I could select the proper software I needed on the Chysler website (Figure 2). I placed my Chysler StarMobile interface on the truck and booted up the WiTech software program to "topology" view with the vehicle online with Chrysler's website. This view is live and provides a lot of information for the working technician with just with one glance at the screen. The controllers are all grouped by different types of networks. Blue lines indicating CAN B, black lines indicating CAN C, gray lines indicating a path to a controller that is not actually on the car, and red



by John Anello,

"The Auto Tech on Wheels

Figure 1: 2007 Jeep Grand Cherokee



Figure 2

lines indicating a dead link to an inoperative controller (Figure 3).You will also notice that any controllers with codes are highlighted in yellow and without codes in blue. If any controllers are in red, they are considered inoperative and off the network. If you look closely, you can see a small green lightning bolt icon on certain controllers indicating that a flash file is available. This is the way a scan tool should be built to really make things easier for the technician. The topology view showed that the PCM was inoperative and I could not communicate with it. The shop techs had the same problem when they hooked up their scan tool, so after performing some checks on the vehicle they determined that the PCM had internal issues. I plugged in the new controller and it didn't respond, either. The shop had also plugged in the new PCM, but they thought it had to be programmed before it would communicate. I explained to them that even



Figure 3

1	Vehicle Roll over an EC	View Outo see full n	ame. Click on	an ECU for complete details.	willow
07 WK 6 N: 1JBHF Ittery:	6.1L R78377C50	2666 volts		Strain and and and and and and and and and an	C
Active I	ECU				
di DTC's	Diagnost	ic Procedure	n Custor	er Preferences Vehicle Preparations	
ale-did row	selection to deve Stored P	environmental dat Versding	tik. Elilik on saturn	r Melading to sort table.	Clear Stored DTC
ble-click row	Stored P	ending Code	ta. Cikik oo colum States	beading to soft table.	Clear Stored DTC
tie-did-row	Stored P ECU ESM	ending Cede U0121	Status active	Heading to sort Table. Description Lost Communication With Anti-Lock Brake Wodule	Clear Stored DTC
die-dio row I Active	Stored P ECU ESM FDCM	ending Cede U0121 U0121	Status active active	Verachy to soft Table Description Lost Communication With Anti-Lock Brake Module Lost Communication With Anti-Lock Brake Module	Clear Stored DTC
de do rov	Stored P Stored P ESM FDCM FDCM	Code U0121 U0121 U0101	Status Status active active active	Vending to soft Table Description Lost Communication With Anti-Lock Brake Module Lost Communication With Anti-Lock Brake Module Lost Communication With TCM	Clear Stored DTC
die did row	ECU ESM FDCM FDCM	Cede Control Control Control Control Control Control Control Control	Status Status active active active active	Verading to soft Table. Description Lost Communication With Anti-Lock Brake Hodule Lost Communication With Anti-Lock Brake Module Lost Communication With TCM Lost Communication With ECM/PCM	Clear Stored DTC
die did row	ECU FDCM FDCM FDCM FDCM FDCM FDCM	Code Code C0525 U0521 U0521 U0500 U0500 U0231	Status Status active active active active active	Verachysts sort rable. Description Lost Communication With Anti-Lock Brake Module Lost Communication With Anti-Lock Brake Module Lost Communication With TCM Lost Communication With ECM/PCM Lost Communication With Light Rain Sensing Module	Clear Stored DTC
deciderow	ECU ESM FDCM FDCM EDM EDM EDM	entromental det ending 00125 00125 00121 00100 00100 00201 00245	Sistes active active active active active active active active	Veraching to sort rable.	Clear Stored DTC
diedd ros ii Active	ECU ESM FDCM FDCM EDM EDM EDM FDCM EDM	Cede Color U0121 U0100 U0100 U0100 U0211 U0245 E2133	Status active active active active active active active active active	Vending to sort rable.	Clear Stored DTC
adiedia nav	ECU ESM FDCM FDCM EDM EDM FDCM FDCM FDCM FDCM FDCM FDCM FDCW FDCGW	Cede Color U0121 U0121 U0100 U0100 U0211 U0245 E2133 P0533	Status active active active active active active active active active active		Clear Stored DTC
abledid row	ECU Stored P ECU ESA FDCA FDCA EDA EDA EDA FDCA EDA FDCA EDA FCACGW FCACGW	Code Code Code Code Code Code Code Code	Status active active active active active active active active active active active active active		Clear Stored DTC

Figure 4

loaded in the new PCM, it still had a boot file in it to allow it to communicate with the scan tool. There was no way I could do the programming without communication with the PCM. When I minimized the topology screen to view the codes below it, there were a lot of "U" codes stored in other controllers in the network because of the PCM failure (Figure 4). The shop had made a bad decision to condemn the old PCM for not communicating with their scan tool. This vehicle had a wiring problem and I would have to pull some diagrams to power-flow system operation prior to my diagnosis.

though no software is

I used Mitchell On Demand to pull a diagram of the PCM (Figure 5). I color-coded the grounds at terminals #9 and # 18 with green , battery feeds at terminals #10 and #29 with red, and ignition feed at terminal #11 with purple. This



Figure 6





Figure 7

The fix here was to replace the entire fuse panel. At this point the only choice I had was to run a temporary feed line to the PCM to validate my findings to see if the car would run and to make sure there weren't any more problems at hand. I jumped out the ignition feed to the PCM with a power source (Figure 10) and the car started and ran fine. I then finalized the diagnosis and went back to my topology view to do a health status on the system (Figute 11). I could now see that the TCM and the ABS modules were also up and running because they most likely shared the same ignition feed that was missing. I could also see that there are flash files available for the PCM and the TCM if the owner of the vehicle decides to do some upgrades.





Figure 10

So, the car was running and there was no need for the new PCM that the shop purchased. Parts suppliers usually won't take back an electrical part, so now the shop owner faced an ethical dilemma. Should he be honest, eat the unnecessary expense and chalk it up

you to be absolutely certain that everything it needs to function is available before you spring for the expense of replacing it. I hope this one hits home with a lot of my readers to always take step back in your diagnostics and make sure you're seeing the big picture.

to a learning experience? Or, should he have me program the new control unit and bury the whole mess without the owner of the vehicle ever knowing what happened? After all, the customer only wants to see the car running no matter what it takes. I know we've all been there, and it is definitely a test of character. How well will your conscience let you sleep at night?

The lesson here is that while the occasional PCM will fail, it behooves



Figure 11