


# 2006 Hyundai Santa Fe Heater Blower LO to HI Speed Voltage and Current Tests

by Agostino (Augie) Ferron








Import Service June 2022





Import Service June 2022



*Import Service* is a publication of Automotive Tech Info. No part of this publication may be reproduced without the express written permission of Automotive Tech Info.

**CAUTION:** VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR OTHERS. INFORMATION CONTAINED IN THIS NEWSLETTER IS INTENDED FOR USE BY TRAINED, PROFESSIONAL AUTO REPAIR TECHNICIANS ONLY. THIS INFORMATION IS PROVIDED TO INFORM THESE TECHNICIANS OF CONDITIONS WHICH MAY OCCUR IN SOME VEHICLES OR TO PROVIDE INFORMATION WHICH COULD ASSIST THEM IN PROPER SERVICING OF THESE VEHICLES. PROPERLY TRAINED TECHNICIANS HAVE THE EQUIPMENT, TOOLS, SAFETY INSTRUCTIONS, AND KNOW-HOW TO PERFORM REPAIRS CORRECTLY AND SAFELY. IF A CONDITION IS DESCRIBED, DO NOT ASSUME THAT A TOPIC COVERED IN THESE PAGES AUTOMATICALLY APPLIES TO YOUR VEHICLE OR THAT YOUR VEHICLE HAS THAT CONDITION.

#### **Publisher**

Tamra Ayers Banz | tbanz@automotivedatamedia.com

### **Editorial Director**

Dick Moritz | dmoritz@automotivedatamedia.com

#### **Technical Writers**

Scott Brown, Dave Facciuto, Agostino (Augie) Ferron, Edwin French, Jordan Hill, Wayne Riley, Gary Smith, Frank Walker

#### **Creative Director**

Christopher Ayers III | ayersc3@automotivedatamedia.com

## **Group Publisher**

Christopher M. Ayers Jr. | cayers@automotivedatamedia.com

# **Circulation Manager**

Joann Turner | jturner@automotivedatamedia.com

# **Editorial and Circulation Office**

134B River Road, Montague, NJ 07827 Phone: 330.620.3929 | <u>importservicemag.com</u>

Where technicians talk to technicians, offering diagnostic tips in 10 minutes or less.

AUTOMOTIVE PORTER AUTOMOTIVE POR

AutomotiveTechInfo.com